

JUC, 10-03-2016, 11.00, Arpad's room

present Jonathan, Des, Arpad

Jonathan: checked address of configuration register in 16 and 32 MHz code, not the same, will fix
Simulations with different clock offsets, found mistake, which is fixed.
Mixing 32 and 16, need swapping bands, can be done in FW or SW. Will check how much work involved, Des and Arpad think it should be far far easier to do it in software.

Des: will ask dr. Bob about 32MHz data.
eBob has made requested changes, but not yet committed. Des also has made some more changes to the UB control code. Test next, then go to operators for breaking code.