Network Monitoring Report: **L-band** # 05/V

Source: 3C273B, J1159-2148, ... **Length:** 120 min. **Observing mode:** Mk IV, mode 256-8-2, dual pol.

Reference antenna: Effelsberg Date of observations: 02/06/05 Reference date: 02/06/05; 153d 16h 00m

According to expectation, no special remarks

Station did not observe (not scheduled)

| | EVN stations Affiliate | | | | | | | | | | | | | | liated | | |
|---|-----------------------------|------------------|------------------------------|---|---|-----------------------|---------------------|------------------------|--------------------------------|-------------------------------|----|------------------|----|----|--------|----------|----|
| | Cm | Ef | $_{ m Jb}$ | Mc | Nt | On | Sh | Tr | Ur | Wb | Ar | Hh | Mh | Yb | Wz | Ro | Sm |
| Station has observed Station produced fringes (ftp) Station produced fringes (disk) | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ | | ⊗ ⊗ ⊗ | | | | | |
| Filled in TRACK Logs are available (within 72 hours) GPS data available (within 7 days) Disks are available (within 7 days) Feedback on www (within 7 days) | | ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ | ⊗ ⊗ ⊗ ⊗ | | ⊗ ⊗ ⊗ ⊗ | | | | | |
| GPS clock estimate gives fringes Clock offset in μ sec Clock rate in psec/sec | \bigotimes 923.849 -0.530 | | \otimes -27.531 -0.530 | $\begin{array}{c} & \otimes \\ -52.704 \\ \hline 1.360 \end{array}$ | $\begin{array}{c} & \otimes \\ -5.251 \\ \hline -0.479 \end{array}$ | ⊗ 34.373 1.000 | | 0.085 0.085 0.0839 | ⊗ 1.553 0.245 | $\bigotimes_{1039.757}$ 0.208 | | 0.070 | | | | <u> </u> | |
| Recording okay | \otimes | \otimes | \otimes | \otimes | \otimes | \otimes | \otimes | \otimes | \otimes | \otimes | | \otimes | | - | | Ī | |
| Polarization setup okay Strong signal amplitude Phase cal aligns phases Please check VC number(s): | ⊗ ⊗ ○ | ⊗ ⊗ ○ | ⊗ ⊗ ○ | ⊗ ⊗ ○ | ⊗ ⊗ ○ | ⊗ ⊗ ○ | ⊗ ⊗ ○ | | \otimes \otimes \bigcirc | ⊗ ⊗ ○ | | ⊗ ⊗ ○ | | | | | |
| Previous reported problem(s) corrected Problem(s) first reported See enclosed footnote(s): | 0 | 0 | 0 | 0 | 0 | 0 | 0 | О а | 0 | 0 | | 0 | | | | | |

Enclosure: Footnotes L-band # 05/V

Footnotes to the Network Monitoring Report: **L-band** # 05/V

General: Place a general comment here

a) Tr, Torun: BBC# 3 was unlocked all the time, resulting in loss of data. Used Rubidium frequency standard, because the H-maser was sent to the manufacturer for refurbishment.

 $Questions?\ anderson@jive.nl$

Report ends