

JUC meeting, 24-4-2014, Arpads room

present Jonathan, Salvatore, Harro, Des, Guifre, Arpad

Jonathan: last weeks bug still there. Maybe in formatting module. Signal tap: works perfectly since. Most probably timing issue. Could synthesize with different seed, try other UB. Leave signal tap in, start tests with 32MHz.

Salvatore: identified three modules that need documentation

Des: tried to fix bug, found bug had disappeared, could not fix it

Guifre: correlated 11 station, 2 pols, 8 bands, all looked wrong, mostly no weights? Harro and Guifre look at data some more. Guifre will redo with 4 bands (which always worked), make sure same channels with SFXC, same VDIF data, use UB that has signal tap in, finally have something to compare.... Des to look at mapping, most likely something wrong there. Arpad: need picture or something for board meeting. Need to start working with Mark5s sending data asap, Guifre will do that. Next week Guifre, Des, Jonathan are not on vacation, help available if needed. Harro, Salvatore and Arpad gone.